# **MAC Diving Tower Replacement -- No. 720702**

Category Culture and Recreation Date Last Modified January 5, 2006
Agency Recreation Required Adequate Public Facility NO

Planning Area Rockville
Relocation Impact None.

				EVECIADILI	ONE SCHE	DOLE (90	00)				
Cost Element	Total	Thru FY05	Est. FY06	Total 6 Years	FY07	FY08	FY09	FY10	FY11	FY12	Beyond 6 Years
Planning, Design						1	U.				
and Supervision	283	0	0	283	95	157	31	0	0	0	0
Land											
Site Improvements											
and Utilities	1,026	0	0	1,026	0	616	410	0	0	0	0
Construction	0	0	0	0	0	0	0	0	0	0	0
Other											
Total	1,309	0	0	1,309	95	773	441	0	0	0	0
				FUNDIN	G SCHEDI	JLE (\$000)	)			, , , , , , , , , , , , , , , , , , ,	
G.O. Bonds	1,309	0	0	1,309	95	773	441	0	0	0	0
			ABIBILIA	LODEDAT	TIMO DUD	CET IMPA	CT (COOO)				

## ANNUAL OPERATING BUDGET IMPACT (\$000)

#### **DESCRIPTION**

The original two 1-meter dive stands, one 3-meter dive stand and 5, 7-1/2 & 10 dive platforms, all made of steel and concrete, are 16 years old. There are three dive platforms as well as a launch for the water flume. The dive stands and three platforms consist of steel pipe columns, tubes, and stringers. The tower and dive platforms receive support from the foundation footings. The horizontal platforms connect to the building superstructure along the north exterior wall of the diving pool. The steel structures of the dive stands and platforms are deteriorating due to corrosion and a consultant was hired to study the causes of corrosion, degree of deterioration and safety analysis.

### Service Area

Rockville

### **JUSTIFICATION**

Consultant's studies revealed that the existing design does not allow proper water drainage, which has created structural deterioration due to corrosion. The degree of corrosion is significant. The consultant strongly recommended for replacement of (a) two 1-meter dive stands, rails and boards, (b) one 3-meter dive stand, rail and board, (c) 5, 7-1/2,&10 meter dive platforms, (d) all piping, electrical components and pumps that are used to operate the water slide, (e) renovate water slide and (f) install a new communication system from the top of the slide to the splash down area for staff communication.

### **STATUS**

Planning

APPROPRIATION AND								
<b>EXPENDITURE DATA</b>								
Date First Appropriation	FY07	(\$000)						
Initial Cost Estimate		0						
First Cost Estimate								
Current Scope	FY07	1,309						
Last FY's Cost Estimate		0						
Present Cost Estimate		1,309						
Appropriation Request	FY07	130						
Appropriation Request Est.	FY08	1,179						
Supplemental								
Appropriation Request	FY06	0						
Transfer		0						
Cumulative Appropriation		0						
Expenditures/								
Encumbrances		0						
Unencumbered Balance		0						
	age Trade of the control of							
Partial Closeout Thru	FY04	0						
New Partial Closeout	FY05	0						
Total Partial Closeout		0						

# COORDINATION

Department of Recreation
Department of Public Works and Transportation
Department of Permitting Services

